

Access Compliance Report Public Rights-of-Way (Curb Ramps)



ntereastion ID: 51572 Main Street: EREEDOM DD				Cross Street, WESLEY, VIII LACE, DD				Location	NE
Intersection ID: 51572	Main Street: FREEDOM_DR			Cross Street: WESLEY_VILLAGE_RD				Location:	
ADA ID: 5CB765AD3D86	: 5CB765AD3D86 Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	SPA M	Possible Solutions:	Compliance Description			Data	Data Compliance Description		Data
and the second sec		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	96.5	Yes	Ramp Slope (%)	6.8
e e e e e e e e e e e e e e e e e e e	A ARA			No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	2.1
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
S S S				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
E .				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		¹		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
L C. To Date L	1 Sector	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	197	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
NODERNA		9		N/A	Shared Landing?	N/A			
A A A A A A A A A A A A A A A A A A A		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	-2-	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A A A A A A A A A A A A A A A A A A A		·····, ····		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
A CALL AND A					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
A stand and a second			N/A	X Walk 1 Width (in)	104.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name FR	EEDOM DR	_			X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

