

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30441 Main Street: ELM BEND_DR Cross Street: CADENCE_CT Location: SE ADA ID: 5CD63F6B159F Ramp Type: NoRamp Initial Pass/Fail: NoRamp Overall Compliance: No Severity Score: 100 Codes/Mitigation Info/Possible Solution Possible Solution: Provide Curb Ramp Provide Curb Ramp Surveyor Notes: N/A N/A PROW/ADA:						
Codes/Mitigation Info/Possible Solution Field Measurements/Compliance Possible Solutions Compliance Description Date Provide Curb Ramp Surveyor Notes: Na Provide Solution Provide Curb Ramp Surveyor Notes: Provide Solution Provide Solution Provide Solution Provide Solution Provide Solution Provide Solution Surveyor Notes: Provide Solution Provide Solution Provide Solution Provide Solution Provide Solution Provide Solution Provide Solution Provide Solution	Intersection ID: 30441	Main Street: ELM_BEND_DR	Cross Street: CADENCE_CT		Location:	SE
Posible Solutions: Provide Curb Ramp Posible Solutions: Provide Curb Ramp Surveyor Notes: N/A PROWADA:	ADA ID: 5CD63F6B159F	Ramp Type: NoRamp	Initial Pass/Fail: NoRamp Overall Complia	nce: No	Severity Score:	100
Provide Curb Ramp Surveyor Notes: N/A PROW/ADA:	Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
		Possible Solutions: Provide Curb Ramp Surveyor Notes: N/A				ata

Total Cost:

1500.00

\$

