

Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 10038417	Main Street: SOUTH_REA_PARK_LN	Cross Street: N/A	Location:	N
ADA ID: 5CE4D97722F4	Ramp Type: BlendTrans1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 0

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance			Description			Data	
	Remove & Replace Curb Slope and Extend Ramp.		N/A	Ramp Length (in)	93.5	Yes	BlendTrans Slope (%)	2.4		
			Yes	Ramp Width (in)	94.5	Yes	BlendTrans XSlope (%)	0.9		
			Yes	Flare Type	LCurbed_NoWalkSurface	Yes	Flare Type	RCurbed_NoWalkSurface		
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No		
			Yes	Landing Length (in)	84.5	Yes	DWS Provided?	Yes		
			Yes	Landing Width (in)	95.0	Yes	DWS Contrast?	Yes		
			Yes	Landing Slope (%)	0.8	Yes	DWS Length (in)	24.0		
			Yes	Landing X Slope (%)	1.0	Yes	DWS Full Width?	Yes		
Surveyor Notes: N/A PROW/ADA: Not Found			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.5		
			N/A	Shared Landing?	No					
			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.1		
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.2		
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
				X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
				X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	N/A		
				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A		
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
			Road Slope (%)	0.9		Clear Space?	Yes			
			Road X Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A			
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No			
			Obstruction Type			Storm Grate/Utility Type				
					N/A		N/A			
					Yes	Surface Condition? (G/P)	Good			
					No	Curb Slope (%)	11.6			

