

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

Intersection ID: 10276	Main Street: ASHLEY_RD			Street:	TUCKASEEGEE_RD	Location:	NW		
ADA ID: 5D29DCF5F6E1	E1 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	and the los	Possible Solutions:		Compliance Description D			ata Compliance Description		Data
	· · · · ·	Remove & Replace Entire Ram	D.	N/A	Ramp Length (in)	126.0	No	Ramp Slope (%)	10.1
al a later and	The House !		P -	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the second second	The shares and			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
The second and the second	B. Com			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		8		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	to the test	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E S	my El	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A CARACTER	1 285			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
-TEIm	b da			N/A	Shared Landing?	N/A			
ASIN	A marta &	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
10	A L DERING	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and a second	Trence 1 1			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	113.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	TUCKASEEGEE RD	_			X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

