

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: STEELE_CREEK_RD				Street:	N/A	Location:	NE			
ADA ID: 5D63D11621E5	Ramp Type: Perp										
· · · ·				initial	Initial Pass/Fail: Fail Overall Compliance: No					15.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	Contract of	Possible Solutions:			Comp	liance Description	Data	Comp	liance Description	Data	
The state of the s	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Remove & Replace Ent	ire Ram	р.	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.0	
					Yes	Ramp Width (in)	60.0	No	Ramp XSlope (%)	2.2	
	Contraction of the				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	1 1 1 1 1 2				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
The A	and the second second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	La is the total				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	A CARACT	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
E. E.	Contraction Cra	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
<u>k</u> .					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	Ale al the				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
21	A MARK AND A				N/A	Shared Landing?	N/A				
La La La	Sa state	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Wallack et	Not Found, R304.2.2, R	304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
ા ના સ્ટેર	There are a set				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	A. S. M. S.					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
	and a state of the				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	STEELE CREEK RD					X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								1			

Yes Surface Condition? (G/P)

Good

