

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10031826 Main Street: MILLWRIGHT_LN Cross Street: N/A Location: SE

ADA ID: 5D65A104A659 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	UNNAMED ALLEY
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

4	TOSSIBLE COLUTION	
	Possible Solutions:	C
	Remove & Replace Entire Ramp.	N
		Ye
		N
		N
		N
		N
	Surveyor Notes:	N.
3	N/A	N.
		N
		N.
15.5		N.
	PROW/ADA:	N.
	Not Found, R304.5.3	N
	·	N
		N
		N

Total Cost:	\$	1850.00







