cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15703	D: 15703 Main Street: CORONADO_DR		Cross Street: N_SHARON_AMITY_RD				Location:	E		
ADA ID: 5D7D44C741F2	F2 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
N. K. A. K. K.		Possible Solutions:		Compliance Description		Data Compliance Description			Data	
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	With	N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	9.2	
				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.7	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
11 28 2 1 11				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Stand 1	111111111			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
S	ALA AL			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	A B ASSA	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
S S S	14.11 4 2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
3			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
			N/A	Shared Landing?	N/A					
	Page 1	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
EX / Castan	No.	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
11/18 3 2			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		
1 Martin	201120				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
A A A A A A A A A A A A A A A A A A A				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	N SHARON AMITY RD				X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	2.4	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	2.0	
Street 2 Name	CORONADO DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign				Road Slope (%)	2.1	N/A	Clear Space?	N/A	
					Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

