

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-		-					
Intersection ID: 47376	Main Street: ARDREY_KELL_RD			Street:	CARSON_WHITLEY_	Location:	SE		
ADA ID: 5D8333702B04	Ramp T	Ramp Type: Perp			ail: Fail Overall	o Severity Score:	33.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 4 182	Remove & Replace Entire Ram	n.	N/A	Ramp Length (in)	71.0	Yes	Ramp Slope (%)	6.0
	hand have		P -	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	7.2
4 2 11/1	111 113	4		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
1019	John M.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
11 31	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Contraction of the second seco			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A On		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A TROAT	1 - 1	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
32	the second			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
1 and the	Was all - 1			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	AND			N/A	Shared Landing?	N/A			
	and the	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 1 Martin Las and		R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
1 Station & State				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Freedom March	A Real and				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
ANT DAG RE 2	1.2.	1		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CARSON WHITLEY AV	_			X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

