

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

29.0

59.0

8.0

2.7

7.6

7.0

N/A

Intersection ID: 10247 Main Street: BURTON ST **Cross Street: WHISNANT ST** Location: **Overall Compliance: No** ADA ID: 5DD77850217C Ramp Type: Combination2 Initial Pass/Fail: Fail Severity Score: 33.75

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Ramp XSlope RT (%)

Data

27.0

61.5

1.7

1.6 No

27.5

42.0

N/A

No

To SE

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name None Stop Condition-Street 1 **BURTON ST** N/A Street 2 Name Stop Condition-Street 2 N/A

Compliance Description Possible Solutions: N/A Remove & Replace Entire Ramp. N/A N/A N/A N/A No Surveyor Notes: N/A LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3 N/A N/A N/A N/A N/A N/A

Total Cost:



X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 3.5 N/A X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 3.8 X Walk 2 X Slope (%) N/A 1600.00 N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 29.3 Curb Slope (%)

