## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20129	9 Main Street: NATIONS_DR		Cross Street: NATIONS_FORD_RD				Location:	NW		
ADA ID: 5DE1DF785A35	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Com			omplian	mpliance: No Severity Score		22.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:					Compliance Description		Data	
		Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	62.0	No	Ramp Slope (%)	8.7	
		Two New Directional Ramps or	VILII	No	Ramp Width (in)	38.0	No	Ramp XSlope (%)	2.9	
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
MATIONS_DR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
the second second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
	1 Marine B	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
A State of the sta	1 2 4 8	R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
a for the second of the	A L SADA			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
La Production and the	11 1 2				X Walk 1 Direction	To S		X Walk 2 Direction	To E	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	NATIONS DR	-			X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	2.0	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	1.3	
Street 2 Name	NATION FORD RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	0.5	N/A	Clear Space?	N/A	
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

es Surface Condition? (G/P)

Good

