

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 15356	Main Street: ARDSLEY_RD	Cross Street: BRUNSWICK_AV	Location: NW
ADA ID: 5DEE04A82B39	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 17.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		N/A	Ramp Length LT (in)	34.0	N/A	Ramp Length RT (in)	33.0
			Yes	Ramp Width LT (in)	69.0	Yes	Ramp Width RT (in)	59.0
			Yes	Ramp Slope LT (%)	1.2	Yes	Ramp Slope RT (%)	6.5
			No	Ramp XSlope LT (%)	2.1	No	Ramp XSlope RT (%)	2.9
			Yes	Landing Length (in)	88.0	No	DWS Provided?	No
			Yes	Landing Width (in)	62.0	N/A	DWS Contrast?	No
			No	Landing Slope (%)	3.3	N/A	DWS Length (in)	N/A
			No	Landing X Slope (%)	6.0	N/A	DWS Full Width?	No
			N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
	Surveyor Notes:		N/A	Shared Landing?	No	Yes	Gutter Slope (%)	4.4
	LT RP < 5%		Yes	Gutter Ponding?	No	No	Gutter X Slope (%)	2.1
			No	Gutter Lip Ht (in)	0.5	N/A	Painted X Walk2?	No
	PROW/ADA:		N/A	Painted X Walk1?	No	N/A	X Walk 2 Direction	To E
	R304.5.3, R304.2.2-Perp, R304.3.2-Para, R305, R302.7.2			X Walk 1 Direction	To S		X Walk 2 Width (in)	N/A
			N/A	X Walk 1 Width (in)	N/A		X Walk 2 Slope (%)	7.2
				X Walk 1 Slope (%)	1.2		X Walk 2 X Slope (%)	1.4
				X Walk 1 X Slope (%)	7.5	N/A	Ramp inside XWalk2?	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Clear Space?	Yes
				Road Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
				Road X Slope (%)	8.4	Yes	Storm Grate/Utility Hazard?	No
			Yes	Any Obstructions?	No		Storm Grate/Utility Type	
				Obstruction Type				
							</	