

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

			-					
Intersection ID: 15639	Main Street: EASTOVER_RD		Cross Street: HEMPSTEAD_PL				Location:	NW
ADA ID: 5E01FFF5BA46	: 5E01FFF5BA46 Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description Da		Data	a Compliance Description		Data
	Remove & Replace Curb	Ramp With	N/A	Ramp Length (in)	57.5	No	Ramp Slope (%)	9.3
C C C C C C C C C C C C C C C C C C C	Two New Directional Ram	nps or	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.3
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	The second second		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1.		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
C. D	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
EVENDER PA 6	Mar and Andrews		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6			N/A	Shared Landing?	N/A			
The state of the second	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	and the second		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	State and State and State			X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name EAS	STOVER RD			X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2	StopSign			X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	0.1
Street 2 Name HEMP	PSTEAD PL		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			Road Slope (%)	2.9	N/A	Clear Space?	N/A
				Road X Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost:	\$ 3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A



