cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10027253 Main Street: GLAZER_VALLEY_CT				Cross	Street:	N/A	Location:	SE		
ADA ID: 5E130EEC2BF1	DA ID: 5E130EEC2BF1 Ramp Type: Perp					nitial Pass/Fail: Pass Overall Compliance: No				0.25
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	A. Maria	Possible Solutions:			Compliance Description		Data Compliance Description		liance Description	Data
BA VI		Remove & Replace En	tire Ram	ip.	N/A	Ramp Length (in)	53.0	Yes	Ramp Slope (%)	6.8
		·		•	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.2
	Aller				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
Alexander of the second s	- A.				N/A	Flare Slope LT (%)	3.2	N/A	Flare Slope RT (%)	6.2
					N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	No
	And the				Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
		Surveyor Notes:			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
L.	Ken Col	N/A			No	Landing Slope (%)	2.2	Yes	DWS Length (in)	24.5
	Calles -				Yes	Landing X Slope (%)	2.2	Yes	DWS Full Width?	Yes
	199 E				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	2.5
	S				N/A	Shared Landing?	No			
aller a start	5. A 1	PROW/ADA:			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.3
The second second	5/ <u>6</u>	Not Found, R304.5.3, F	R304.2.2	Perp.	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.0
	B .	R304.3.2-Para, R305.2		[-,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	STAL A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
	1 hours				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GLAZER VALLEY CT					X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	Yes
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

