


Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: E_4TH_ST **Cross Street: N/A** Location: N ADA ID: 5E2CAFF4F58E Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 27.5

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

E 4TH ST None **ENTRANCE** None

Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.3, R302.7

Total Cost: 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Data	
	N/A	Ramp Length (in)	53.0	Yes	Ramp	Slope (%)	6.0
	Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	5.4
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
		X Walk 1 Direction	To SW		X Wal	k 2 Direction	To SE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
		X Walk 1 Slope (%)	1.7		X Wal	k 2 Slope (%)	0.9
		X Walk 1 X Slope (%)	0.1		X Wal	k 2 X Slope (%)	1.5
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road Slope (%)	0.5	N/A	Clear	Space?	N/A
		Road X Slope (%)	2.1	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
		Obstruction Type			Storm	Grate/Utility Type	
			N/A				N/A
				No	Surfac	ce Condition? (G/P)	Poor
_							





