


Intersection ID: 5553	Main Street: HAWKINS_PL	Cross Street: ROCKWELL_BV	Location:	W
ADA ID: 5E2F8DB34684	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 12.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	N/A	N/A	Ramp Length RT (in)	70.0
			N/A	Ramp Width LT (in)	N/A	No	Ramp Width RT (in)	35.0
			N/A	Ramp Slope LT (%)	N/A	No	Ramp Slope RT (%)	11.3
			N/A	Ramp XSlope LT (%)	N/A	Yes	Ramp XSlope RT (%)	0.6
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Surveyor Notes:			N/A	Shared Landing?	N/A			
N/A			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
PROW/ADA:			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
R304.5.1, R304.3.2			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	7.5		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
				Obstruction Type			Storm Grate/Utility Type	
Total Cost:		\$ 1600.00			N/A			N/A
						Yes	Surface Condition? (G/P)	Good
						N/A	Curb Slope (%)	13.1

