

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			_					Location:	
Intersection ID: 50618	Main Str	Main Street: YELLOW_OAK_RD			Cross Street: ABNEY_CT				N
ADA ID: 5E3F405F438C	Ramp Ty	Ramp Type: Perp			ail: Fail Overall	nce: N	o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	47.5	No	Ramp Slope (%)	8.4
		-		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.3
	A			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	AN AN			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
- SHE				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the of the second	S A			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A Do	and the second	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Mallon B.		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A A A A A A A				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The state of the state	A PARTY	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The statement of the co	Ch .	,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	1 Alina				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	YELLOW OAK RD				X Walk 1 Slope (%)	4.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

