


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 20750	Main Street: LANSDOWNE_RD	Cross Street: PRETT_CT	Location: S
ADA ID: 5E600AC28D93	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		No	Ramp Length (in)	47.0
			Yes	Ramp Width (in)	78.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2, R304.5.3</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
<p>Total Cost:</p> <p>\$ 3200.00</p>			No	Painted X Walk2?	No
			To NE	X Walk 2 Direction	To NW
			N/A	X Walk 2 Width (in)	N/A
			1.5	X Walk 2 Slope (%)	1.5
			0.8	X Walk 2 X Slope (%)	1.7
			N/A	Ramp inside XWalk2?	N/A
			1.0	Clear Space?	N/A
			6.8	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
<p>Street 1 Name</p> <p>PRETT CT</p> <p>Stop Condition-Street 2</p> <p>StopSign</p> <p>Street 2 Name</p> <p>LANSDOWNE RD</p> <p>Stop Condition-Street 1</p> <p>None</p>			N/A	Surface Condition? (G/P)	Good
			N/A		

