cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15991	section ID: 15991 Main Street: BUNCHE_DR				WHEATLEY_AV	Location:	NE		
ADA ID: 5ED039D484E2				Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200 - 200		Possible Solutions:					Comp	Compliance Description Data	
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	55.0	Yes	Ramp Slope (%)	8.1
		Two New Directional Ramps or Equivalent.	-	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.0
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A And a			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the Charles of the second		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
WHEATLEY_AV				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the state of the s			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
a day 1 & was transmith			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To W		X Walk 2 Direction	To S
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	BUNCHE DR	-			X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	6.8
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.4		X Walk 2 X Slope (%)	3.6
Street 2 Name	WHEATLEY AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	4.1	N/A	Clear Space?	N/A
					Road X Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

