

Intersection ID: 18818	Main Street: BEAM_RD	Cross Street: SHOPTON_RD	Location:	SW
ADA ID: 5F24C6DB28B5	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 13.75

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
-----------------------------------------	-----------------------------------------



### Possible Solutions:

### Remove & Replace Entire Ramp.

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.2.2, R304.5.3**

Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	9.1		
	Yes	Ramp Width (in)	94.0	No	Ramp XSlope (%)	2.1		
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
	N/A	Shared Landing?	N/A					
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Surveyor Notes:  N/A	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
		X Walk 1 Direction	To E		X Walk 2 Direction	N/A		
	N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A		
		X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A		
		X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A		
	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
		Road Slope (%)	N/A	N/A	Clear Space?	N/A		
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
		Obstruction Type			Storm Grate/Utility Type			
			N/A			N/A		
			Yes	Surface Condition? (G/P)	Good			
Total Cost:			\$	1850.00				

Street 1 Name	BEAM RD
Stop Condition-Street 2	YieldSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

