

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7185 Main Street: S_I-85_EXIT_41_RA Cross Street: W_SUGAR_CREEK_RD Location: ADA ID: 5F5FB40E6493 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



S I-85 EXIT 41 RA Street 1 Name Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/
	Ye
	N/A
	N/
	N/
	N/
Surveyor Notes:	N/A
N/A	N/
	N/
	N/
	N/
PROW/ADA:	N/
Not Found, R304.2.2	N/A
	N/A
	N/A

1850.00

Field Measurements/Component Compliance								
Com	pliance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	29.0	No	Ramp	Slope (%)	9.0		
Yes	Ramp Width (in)	55.0	Yes	Ramp	XSlope (%)	1.4		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	120.0	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.2		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.8		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		





Total Cost:

