

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

52.0

83.0

1.7

1.1

4.5

4.6

N/A

Intersection ID: 14312 Main Street: W TYVOLA RD **Cross Street: SHADY LN** Location: Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 5FE2A17483D9 Ramp Type: Combination1 Severity Score: 13.75

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Data

58.0

82.0

11.1

1.7

30.0

48.0

N/A

No

To SW

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp XSlope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

Flare Traversable LT?

Flare Type LT



StopSign Street 1 Name Stop Condition-Street 1 SHADY LN N/A Street 2 Name Stop Condition-Street 2 N/A

Compliance Description Possible Solutions: N/A Remove & Replace Entire Ramp. Yes No Yes N/A Yes Surveyor Notes: N/A **RT RP < 5%** N/A N/A N/A N/A PROW/ADA: N/A R304.5.3, R304.3.2 N/A N/A N/A N/A N/A

Total Cost:



N/A

X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 2.7 X Walk 2 Slope (%) N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 5.2 X Walk 2 X Slope (%) N/A 1800.00 N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 4.5

