

Access Compliance Report Public Rights-of-Way (Curb Ramps)



\cdot \cdot									
Intersection ID: 21296	Main Street: E_ARROWOOD_RD			Cross Street: OLD_PINEVILLE_RD				Location:	NE
ADA ID: 6019EB3AC282	DA ID: 6019EB3AC282 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	SAX FOLL	Possible Solutions:		Compliance Description			Data Compliance Description		
AMAGES	Line 1	Remove & Replace Entire R	Ramp.	N/A	Ramp Length (in)	104.0	No	Ramp Slope (%)	8.8
	LA DELAN			Yes	Ramp Width (in)	69.0	Yes	Ramp XSlope (%)	1.4
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	his his			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	No no	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
L B mmmL L	proventing to any	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	D_RD4 100 (A1 🖘			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	WE A WE ME	5		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
a an grant b	2019年1月2日			N/A	Shared Landing?	N/A			
PROW/ADA:				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A CONTRACTOR	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	2 Det annu			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
The state				X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
			N/A	X Walk 1 Width (in)	114.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	E ARROWOOD RD	-			X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1850.	00	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							•		

Yes Surface Condition? (G/P)

Good

