


Intersection ID: 8908	Main Street: RUSSELL_AV	Cross Street: WELCH_PL	Location:	SE
ADA ID: 60E882EE65E7	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 1.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance													
	Possible Solutions:					Compliance			Description			Data				
	Remove & Replace Entire Ramp.					N/A			Ramp Length (in)			60.0				
						Yes			Ramp Width (in)			60.0				
						N/A			Flare Type LT			N/A				
						N/A			Flare Slope LT (%)			N/A				
						N/A			Flare Traversable LT?			N/A				
						N/A			Landing Length (in)			N/A				
						N/A			Landing Width (in)			N/A				
						N/A			Landing Slope (%)			N/A				
						N/A			Landing X Slope (%)			N/A				
Surveyor Notes:					N/A			N/A			DWS Provided?			N/A		
								N/A			DWS Contrast?			N/A		
								N/A			DWS Length (in)			N/A		
								N/A			DWS Full Width?			N/A		
								N/A			DWS Offset (in)			N/A		
								N/A								
PROW/ADA:					Not Found, R304.5.3			N/A			Gutter Ponding?			N/A		
								N/A			Gutter Lip Ht (in)			N/A		
								N/A			Painted X Walk1?			No		
											X Walk 1 Direction			To W		
								N/A			X Walk 1 Width (in)			N/A		
											X Walk 1 Slope (%)			2.4		
											X Walk 1 X Slope (%)			1.2		
								N/A			Ramp inside XWalk1?			N/A		
											Road Slope (%)			N/A		
											Road X Slope (%)			N/A		
								N/A			Any Obstructions?			N/A		
											Obstruction Type					
														N/A		
														Yes		
														Surface Condition? (G/P)		
														Good		

Street 1 Name

Stop Condition-Street 2

Street 2 Name

Stop Condition-Street 1

WELCH PL

StopSign

N/A

N/A

Total Cost:

\$

1850.00

