

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 5704	Main Street: W W T HARRIS BV	Cross Street: N TRYON ST	Location:	E
ADA ID: 60FDD98A408F	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 20
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance		



Possible Solutions:

**Remove & Replace Curbed Edge.
Grind Gutter Lip.**

Surveyor Notes:

LOCATED ON MEDIAN

PROW/ADA:

R304.2.3, R302.7.2

Total Cost:

\$ 500.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	85.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	120.0	Yes	Grade Break Slope (%)	1.3
Yes	Ramp Slope (%)	6.8	Yes	Grade Break XSlope (%)	1.4
Yes	Ramp XSlope (%)	0.1			
No	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	112.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	120.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.5	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.6	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	0.0
N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	26.5
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.6
No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	1.4
N/A	Painted X Walk1?	No		Road Slope (%)	3.3
	X Walk 1 Direction	To W		Road X Slope (%)	0.8
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.8	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	N/A

