

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

11.0

0.1

N/A

N/A

N/A

N/A

N/A

Intersection ID: 8329 Main Street: BEATTIES FORD RD **Cross Street: LASALLE ST** Location: NE ADA ID: 616A5E85967C

Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

Flare Traversable LT?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

N/A

N/A

N/A N/A

N/A N/A

Data

80.0

41.5

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

Flare Traversable RT?

Flare Type RT



LASALLE ST Street 1 Name Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A

<u>,,</u>	i ossible ociution			I ICIG IVIC
1	Possible Solutions:	Complia	ance	Description
The same	Remove & Replace Entire Ramp.	N/A	Ramp	Length (in)
4	·	No	Ramp	Width (in)
S. Shell		N/A	Flare	Type LT
100		N/A	Flare	Slope LT (%)
8		N/A	Flare	Traversable LT
		N/A	Landir	ng Length (in)
	Surveyor Notes:	N/A	Landir	ng Width (in)
1	N/A	N/A	Landir	ng Slope (%)
4		N/A	Landir	ng X Slope (%)
		N/A	Landir	ng Curb? (Y/N)
2		N/A	Share	d Landing?
	PROW/ADA:	N/A	Gutte	Ponding?
1	Not Found, R304.5.1, R304.2.2	N/A	Gutte	Lip Ht (in)
The state of		N/A	Painte	ed X Walk1?
1			X Wal	k 1 Direction
		N/A	X Wal	k 1 Width (in)
			X Wal	k 1 Slope (%)
			X Wal	k 1 X Slope (%
		N/A	Ramp	inside XWalk1
			Road	Slope (%)

			N/A
Surveyor Notes:			N/A
N/A			N/A
			N/A
			N/A
			N/A
PROW/ADA:			N/A
Not Found, R304.5.1, R3	04.2.2	<u>></u>	N/A
			N/A
Total Cost:	\$	1850.00	

		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To S		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	121.0	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A
		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
\$	1850.00		Obstruction Type		l	Storm Grate/Utility Type	
				N/A			N/A
					Yes	Surface Condition? (G/P)	Good
		Water	Red				





