

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12687Main Street:BROWNING_AVCross Street:NASSAU_BVLocation:NEADA ID: 617ABD4534B8Ramp Type:BlendTrans1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 1

StopSign

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Yes BlendTrans Slope (%) N/A Ramp Length (in) 75.0 1.7 46.5 No No Ramp Width (in) BlendTrans XSlope (%) 2.1 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To S X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 5.5 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 1.7 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? N/A Road Slope (%) 1.7 Clear Space? N/A Road X Slope (%) 5.5 N/A Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good No 18.6 Curb Slope (%)





