

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28484 Main Street: ELM LN Cross Street: WINDSOR RIDGE DR Location: NE ADA ID: 618266454847 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution



ELM LN Street 1 Name Stop Condition-Street 2 None Street 2 Name WINDSOR RIDGE DR Stop Condition-Street 1 StopSign

Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.3

Total Cost: 3200.00

Field Measurements/Component Compliance						
	Compliance Description		Data	Comp	oliance Description	Data
	N/A	Ramp Length (in)	52.0	Yes	Ramp Slope (%)	7.9
	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.0
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	7.6		X Walk 2 Slope (%)	1.6
		X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	5.8
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	2.3	N/A	Clear Space?	N/A
		Road X Slope (%)	1.5	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
	1 1 1 W					





