


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A		Main Street: ARDREY_KELL_RD		Cross Street: WAVERLY_WALK_AV		Location: NW			
ADA ID: 61D9754A1CA2		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 0	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance		Description		Data	
		Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	94.0	No	Grade Break?	No
				Yes	Ramp Width (in)	95.0	N/A	Grade Break Slope (%)	4.2
				Yes	Ramp Slope (%)	6.2	N/A	Grade Break XSlope (%)	0.1
				Yes	Ramp XSlope (%)	0.7			
				Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
				Yes	Landing Length (in)	96.0	Yes	DWS Provided?	Yes
				Yes	Landing Width (in)	95.0	Yes	DWS Contrast?	Yes
Surveyor Notes: N/A				Yes	Landing Slope (%)	0.1	Yes	DWS Length (in)	24.0
				Yes	Landing X Slope (%)	0.0	Yes	DWS Full Width?	Yes
				N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	40.0
				N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	0.0
				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.0
				Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.8
				N/A	Painted X Walk1?	Yes		Road Slope (%)	3.5
					X Walk 1 Direction	To S		Road X Slope (%)	1.0
					X Walk 1 Width (in)	113.0		Clear Space?	Yes
					X Walk 1 Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A
PROW/ADA: Not Found, R304.5.2					X Walk 1 X Slope (%)	1.0	Yes	Storm Grate/Utility Hazard?	No
				Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
				Yes	Any Obstructions?	No			N/A
					Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	No	Curb Slope (%)	8.5

Compliance	Description	Data	Compliance	Description	Data
No	Grade Break?	No	No	Grade Break?	No
Yes	Grade Break Slope (%)	4.2	N/A	Grade Break Slope (%)	4.2
Yes	Grade Break XSlope (%)	0.1	N/A	Grade Break XSlope (%)	0.1
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	96.0	Yes	Landing Width (in)	95.0
Yes	Landing Width (in)	95.0	Yes	Landing Slope (%)	0.1
Yes	Landing Slope (%)	0.1	Yes	Landing X Slope (%)	0.0
Yes	Landing X Slope (%)	0.0	Yes	Landing Curb? (Y/N)	N/A
N/A	Landing Curb? (Y/N)	N/A	Yes	Shared Landing?	Yes
N/A	Shared Landing?	Yes	Yes	Gutter Ponding?	No
Yes	Gutter Ponding?	No	Yes	Gutter Lip Ht (in)	0.0
Yes	Gutter Lip Ht (in)	0.0	Yes	Painted X Walk1?	Yes
N/A	Painted X Walk1?	Yes		X Walk 1 Direction	To S
	X Walk 1 Direction	To S		X Walk 1 Width (in)	113.0
	X Walk 1 Width (in)	113.0		X Walk 1 Slope (%)	3.5
	X Walk 1 Slope (%)	3.5	N/A	X Walk 1 X Slope (%)	1.0
	X Walk 1 X Slope (%)	1.0	Yes	Ramp inside XWalk1?	Yes
Yes	Ramp inside XWalk1?	Yes	Yes	Any Obstructions?	No
Yes	Any Obstructions?	No		Obstruction Type	
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
N/A	Surface Condition? (G/P)	Good	N/A	Curb Slope (%)	8.5
N/A	Curb Slope (%)	8.5	No		

