

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49140Main Street:POPE_FARM_RDCross Street:CEMKEY_WAY_CTLocation:SWADA ID: 61EB65FF70E6Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	CEMKEY WAY CT
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

o/Possible Solution		Field Measurements/Component Compliance							
Possible Solutions:		Comp	liance Description	Data	Comp	liance	Description	Data	
Remove & Replace Entire Ra	ımp.	N/A	Ramp Length (in)	48.0	Yes	Ramp	Slope (%)	5.4	
	-	No	Ramp Width (in)	43.0	Yes	Ramp	XSlope (%)	3.5	
		N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
5		N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A		N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
		N/A	Shared Landing?	N/A					
PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A	
Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A	
			X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	2.5		X Wa	lk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	3.6		X Wa	lk 2 X Slope (%)	N/A	
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A	
			Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
			Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A	
Total Cost: \$	1850.00		Obstruction Type			Storm	n Grate/Utility Type		
				N/A				N/A	
					Yes	Surfa	ce Condition? (G/P)	Good	





