

Access Compliance Report


Public Rights-of-Way

(Curb Ramps)

| | | | |
|----------------------|----------------------------|--------------------------------|------------------------|
| Intersection ID: N/A | Main Street: ARBOR_LOOP_DR | Cross Street: ANSLEY_GARDEN_DR | Location: SW |
| ADA ID: 6235383883E1 | Ramp Type: Directional1 | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | Severity Score: 1.25 | |

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost:

\$ 1600.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 85.0 | N/A | Grade Break? | N/A |
| Yes | Ramp Width (in) | 69.0 | N/A | Grade Break Slope (%) | 0.0 |
| Yes | Ramp Slope (%) | 5.5 | N/A | Grade Break XSlope (%) | 0.0 |
| No | Ramp XSlope (%) | 2.9 | | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A |
| N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A |
| N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | Yes | | Road Slope (%) | 1.7 |
| | X Walk 1 Direction | To E | | Road X Slope (%) | 0.8 |
| | X Walk 1 Width (in) | 65.5 | | Clear Space? | N/A |
| | X Walk 1 Slope (%) | 1.7 | N/A | Clear Space to XWalk (in) | N/A |
| | X Walk 1 X Slope (%) | 0.8 | N/A | Storm Grate/Utility Hazard? | N/A |
| N/A | Ramp inside XWalk1? | Yes | | Storm Grate/Utility Type | |
| N/A | Any Obstructions? | N/A | | | N/A |
| | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | | N/A | Curb Slope (%) | 7.3 |

