

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040110Main Street: TUCKASEGEE_RDCross Street: N/ALocation:NADA ID: 6245687ADCEDRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	TUCKASEEGEE RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	
Remove & Replace Entire Ramp.	ı
	I
	1
Surveyor Notes:	i
N/A	ı
	I
	I
	ı
PROW/ADA:	I
Not Found, R304.5.1, R304.2.2	!
	ı
	ı
	,

	in .	7	10. 3
		1.5	
	THE RESERVE THE PROPERTY OF TH		
15	\		
it for	1		

Total Cost:



1850.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	71.0	No	Ramp	Slope (%)	8.6
No	Ramp Width (in)	47.0	Yes	Ramp	XSlope (%)	0.4
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	Yes	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.8		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.3		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
	••	N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good
			•		` ,	