


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 14314	Main Street: E_TREMONT_AV	Cross Street: SOUTH_BV	Location: SW
ADA ID: 62674E78C33F	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 10.25

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Remove & Replace Entire Ramp. Remove & Replace Gutter.					
	Surveyor Notes:	N/A					
	PROW/ADA:	Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305.2					
	Street 1 Name	SOUTH BV					
	Stop Condition-Street 2	Signal					
	Street 2 Name	N/A					
	Stop Condition-Street 1	N/A					
	Total Cost:	\$	2600.00				

Street 1 Name	SOUTH BV
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Total Cost: \$ 2600.00

