

Intersection ID: 11267	Main Street: DRUMMOND_AV	Cross Street: DUNCAN_AV	Location:	SE
ADA ID: 627D34D987EF	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 30

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance									
	Possible Solutions:		Compliance			Description			Data			
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		62.5		No	Ramp Slope (%)		9.4	
			No	Ramp Width (in)		32.0		Yes	Ramp XSlope (%)		0.4	
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A	
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		N/A	
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A	
			N/A	Landing Length (in)		N/A		N/A	DWS Provided?		N/A	
			N/A	Landing Width (in)		N/A		N/A	DWS Contrast?		N/A	
			N/A	Landing Slope (%)		N/A		N/A	DWS Length (in)		N/A	
			N/A	Landing X Slope (%)		N/A		N/A	DWS Full Width?		N/A	
Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1	Surveyor Notes:		N/A	Landing Curb? (Y/N)		N/A		N/A	DWS Offset (in)		N/A	
	N/A		N/A	Shared Landing?		N/A						
	PROW/ADA:		N/A	Gutter Ponding?		N/A		N/A	Gutter Slope (%)		N/A	
	Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)		2.0		N/A	Gutter X Slope (%)		N/A	
			N/A	Painted X Walk1?		No		N/A	Painted X Walk2?		N/A	
				X Walk 1 Direction		To W			X Walk 2 Direction		N/A	
			N/A	X Walk 1 Width (in)		N/A		N/A	X Walk 2 Width (in)		N/A	
				X Walk 1 Slope (%)		3.2			X Walk 2 Slope (%)		N/A	
				X Walk 1 X Slope (%)		2.3			X Walk 2 X Slope (%)		N/A	
			N/A	Ramp inside XWalk1?		N/A		N/A	Ramp inside XWalk2?		N/A	
			Road Slope (%)		N/A		N/A	Clear Space?		N/A		
			Road X Slope (%)		N/A		N/A	Clear Space to XWalk (in)		N/A		
		N/A	Any Obstructions?		N/A		N/A	Storm Grate/Utility Hazard?		N/A		
			Obstruction Type					Storm Grate/Utility Type				
							N/A			N/A		
								Yes		Surface Condition? (G/P) Good		
Total Cost:		\$ 1850.00										

