

Access Compliance Report Public Rights-of-Way (Curb Ramps)



\cdot										
Intersection ID: 10037314 Main St		reet: SARDIS_RD	Cross Street: N/A					Location:	SE	
ADA ID: 62A3EB88DD87 Ramp Ty		ype: Directional1	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description Dat			a Compliance Description		Data	
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	93.5	N/A	Grade Break?	N/A	
				Yes	Ramp Width (in)	83.0	N/A	Grade Break Slope (%)	0.0	
				Yes	Ramp Slope (%)	3.6	N/A	Grade Break XSlope (%)	0.0	
				No	Ramp XSlope (%)	4.2				
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	1.1.2	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	1	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
E A				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	and the second	*		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
EXIC- TO MARKE		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	3.1	
Street 1 Name	ENTRANCE				X Walk 1 Direction	To N		Road X Slope (%)	4.4	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.4	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	15.0	

