

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: BOYCE_RD Cross Street: TOBIN_CT Location: NW

ADA ID: 62D0DC75D015 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 46.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	TOBIN CT
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

o/Possible Solution		Field Measurements/Component Compliance					
Possible Solutions:	Com	pliance Description	Data	Comp	liance Description	Data	
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	74.0	N/A	Grade Break?	N/A	
•	No	Ramp Width (in)	47.0	N/A	Grade Break Slope (%)	0.0	
	No	Ramp Slope (%)	8.9	N/A	Grade Break XSlope (%)	0.0	
	No	Ramp XSlope (%)	7.0				
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A CONTRACTOR OF THE CONTRACTOR	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
Surveyor Notes:	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
PROW/ADA:	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
R304.5.1, R304.2.2, R304.5.3	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
,	N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	No		Road Slope (%)	5.2	
		X Walk 1 Direction	To E		Road X Slope (%)	4.3	
		X Walk 1 Width (in)	N/A		Clear Space?	N/A	
		X Walk 1 Slope (%)	5.2	N/A	Clear Space to XWalk (in)	N/A	
		X Walk 1 X Slope (%)	4.3	N/A	Storm Grate/Utility Hazard?	N/A	
	N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
	N/A	Any Obstructions?	N/A			N/A	
Total Cost: \$ 1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
			N/A	N/A	Curb Slope (%)	2.3	
				-			





