


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 26952	Main Street: PROVIDENCE_CHURCH_LN	Cross Street: SARAH_HALL_LN	Location: NE
ADA ID: 62D4F8392CF7	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance			Description			Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	61.0	N/A	Ramp Length RT (in)	51.0		
			Yes	Ramp Width LT (in)	72.0	Yes	Ramp Width RT (in)	72.0		
			No	Ramp Slope LT (%)	9.3	Yes	Ramp Slope RT (%)	2.9		
			No	Ramp XSlope LT (%)	3.1	No	Ramp XSlope RT (%)	2.4		
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
Surveyor Notes:		RT RP < 5%			N/A			N/A		
PROW/ADA:		R304.3.2, R304.5.3			N/A			N/A		
		N/A			No			N/A		
		N/A			To S			N/A		
		N/A			N/A			N/A		
		N/A			3.2			N/A		
		N/A			2.3			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		
		N/A			N/A			N/A		

