

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2475 Main Street: HIGHLAND_CREEK_PY Cross Street: WILDBROOK_DR Location: N

ADA ID: 63134546FDBE Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WILDBROOK DR StopSign HIGHLAND CREEK PY None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2

Total Cost: \$ 3200.00

Compliance Description Data		Comp	liance	Description	Data	
N/A	Ramp Length (in)	79.0	No	Ramp	Slope (%)	8.9
No	Ramp Width (in)	46.0	Yes	Ramp	XSlope (%)	0.9
N/A	Flare Type LT	N/A	N/A	Flare ⁻	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare ⁻	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Walk 1 Direction	To SW		X Wall	k 2 Direction	To SE
N/A	X Walk 1 Width (in)	N/A	N/A	X Wall	k 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.5		X Wall	k 2 Slope (%)	3.0
	X Walk 1 X Slope (%)	1.9		X Wall	k 2 X Slope (%)	1.7
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	1.0	N/A	Clear	Space?	N/A
	Road X Slope (%)	2.7	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfac	ce Condition? (G/P)	Good





