


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 48417	Main Street: WINDS_CROSSING_DR	Cross Street: CAROWINDS_BV	Location: SW
ADA ID: 63529E243BA7	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:								
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.								
	Surveyor Notes:								
	N/A								
	PROW/ADA:								
	Not Found, R304.5.1, R304.2.2, R304.5.3								
	Street 1 Name		CAROWINDS BV		Compliance		Description		Data
	Stop Condition-Street 2		None		N/A		Ramp Length (in)		48.0
	Street 2 Name		WINDS CROSSING DR		No		Ramp Width (in)		47.0
	Stop Condition-Street 1		StopSign		N/A		Flare Type LT		N/A
				N/A		Flare Slope LT (%)		N/A	
				N/A		Flare Type RT		N/A	
				N/A		Flare Slope RT (%)		N/A	
				N/A		Flare Traversable LT?		N/A	
				N/A		Flare Traversable RT?		N/A	
				N/A		DWS Provided?		N/A	
				N/A		DWS Contrast?		N/A	
				N/A		DWS Length (in)		N/A	
				N/A		DWS Full Width?		N/A	
				N/A		DWS Offset (in)		N/A	
				N/A		Shared Landing?		N/A	
				N/A		Gutter Ponding?		N/A	
				N/A		Gutter Lip Ht (in)		N/A	
				N/A		Painted X Walk1?		No	
				To E		X Walk 2 Direction		To NW	
		N/A		N/A		X Walk 2 Width (in)		N/A	
				2.4		X Walk 2 Slope (%)		1.4	
				1.2		X Walk 2 X Slope (%)		6.5	
		N/A		N/A		Ramp inside XWalk2?		N/A	
				3.8		Clear Space?		N/A	
				3.4		Clear Space to XWalk (in)		N/A	
		N/A		N/A		Storm Grate/Utility Hazard?		N/A	
				N/A		Storm Grate/Utility Type			
				N/A				N/A	
				Yes		Surface Condition? (G/P)		Good	
Total Cost:		\$ 3200.00							

