

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

51.0

71.0

9.9

1.8

8.8

1.6

N/A

N/A

N/A

0.5

Good

Intersection ID: N/A Main Street: MCCLINTOCK RD **Cross Street: N/A** Location: SE Initial Pass/Fail: Fail **Overall Compliance: No** 22.5 ADA ID: 6386D84DF526 Ramp Type: Combination1 **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

No

Yes

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

Claus Tussiansable DTO

Surface Condition? (G/P)

Curb Slope (%)

Flare Type RT

Data

54.0

87.0

6.1

3.1

150.0

46.0

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name None Stop Condition-Street 1 MCCLINTOCK RD Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions: Compliance Description Remove & Replace Entire Ramp. N/A Yes Yes No N/A No Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.5.1, R304.2.2, R304.5.3, N/A R304.3.2 N/A N/A N/A N/A N/A



Total Cost:



1800.00

Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstruction?	N/A
			Obstruction Type	
The state of the s				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
			Storm Grate/Utility Type	
	Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%)	Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? N/A Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? N/A N/A	Landing Length (in) Landing Width (in) N/A Landing Slope (%) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Vidth (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? N/A Road Slope (%) N/A N/A N/A N/A N/A	Landing Length (in) Landing Width (in) Landing Slope (%) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) N/A Road X Slope (%) N/A N/A N/A N/A N/A DWS Full Width? N/A N/A DWS Offset (in) N/A Gutter Slope (%) N/A N/A Gutter X Slope (%) N/A Painted X Walk2? X Walk 2 Direction X Walk 2 Width (in) X Walk 2 Slope (%) X Walk 2 X Slope (%) N/A Ramp inside XWalk2? Clear Space? N/A N/A Clear Space to XWalk (in) N/A Any Obstruction? Obstruction Type N/A Storm Grate/Utility Hazard?

Yes