cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31542	Main Str	eet: ALMORA_DR		Cross Street: OLD_PLANK_RD				Location:	SE
ADA ID: 6395F0BF418C	Ramp Ty	pe: Combination1		Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 1		10
Code	es/Mitigation Info/	Possible Solution			Field Measure	ements/Co	ompo	nent Compliance	
		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
	A MARINE	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	51.0	N/A	Ramp Length RT (in)	41.0
A. 199				No	Ramp Width LT (in)	47.0	Yes	Ramp Width RT (in)	48.0
And the	SP .			Yes	Ramp Slope LT (%)	3.1	Yes	Ramp Slope RT (%)	5.2
				No	Ramp XSlope LT (%)	3.6	No	Ramp XSlope RT (%)	2.8
				N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	7.3
	1 T .			No	Ramp Width (in)	44.0	Yes	Ramp XSlope (%)	1.6
6.		Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		RP & LT RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Here and the second sec				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
- A A A A A A A A A A A A A A A A A A A				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Mar .	Not Found, R304.5.1, R304.5.1,	. R304.5.1.	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
AND A SHE WAS A	Carlos A	R304.5.3	, ,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
ALL				N/A	Shared Landing?	N/A			
and the second second	Trank 1			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	ALOMORA DR			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A
					X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 1800	0.00 N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	N/A		Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
							N/A	Any Obstruction?	N/A
the second second	ALTUNA AN A	in the second		ALTON #				Obstruction Type	
		A CONTRACTOR							N/A
				JK CONTRACTOR			N/A	Storm Grate/Utility Hazard?	N/A
			The second secon	A A AND				Storm Grate/Utility Type	11/17

Storm Grate/Utility Type
N/A
Yes Surface Condition? (G/P) Good
Curb Slope (%) 11.0





