

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7436	Main St	Cross Street: CARRIER DR					Location:	NE	
								NE	
ADA ID: 63D3DAF81E28	8 Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	The state	Possible Solutions:	Compliance Description			Data	Data Compliance Description Dat		
1 3 11 3 REAL VER H	AN NO	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	8.4
	1411 48			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.6
South States And Plan	山村二		I	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Freedom I. I. P. Starra	118 1	2		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
and the second second	17 10 1			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
The state and a state of the second	1. 1. 230	C		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	1 minut	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the sector	MORELAND	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N_HOSKINS_RD	CONTRACTOR OF			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	A	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	21 4	Not Found, R304.2.2, R304.5.3	I	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	1 and 1 and	3			X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
Sheriffelle	- 34			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name N H	IOSKINS RD				X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

es Surface Condition? (G/P)

Good

