

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11271 Main Street: CATAWBA\_AV Cross Street: PEGRAM\_ST Location: SE

ADA ID: 6414EC41D11B Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance



Street 1 Name PEGRAM ST
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

School	Possible Solutions:
4	Remove & Replace Entire Ramp.
100	
1	
Sec.	
130	
100	Surveyor Notes:
9	N/A
9	
9	DDOW/ADA.
	PROW/ADA:
M. 15	Not Found, R304.5.1, R304.2.2
Sections	

Total Cost: \$ 1850.00

Comp	oliance Description	Data	ta Compliance Des		otion	Data
N/A	Ramp Length (in)	65.0	No	Ramp Slope (	%)	9.2
No	Ramp Width (in)	45.5	Yes	Ramp XSlope	(%)	0.2
N/A	Flare Type LT	N/A	N/A	Flare Type RT	-	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope R	T (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversa	able RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided	d?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contras	t?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (	(in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Wid	th?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (i	n)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (	(%)	N/A
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope	e (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Wa	lk2?	N/A
	X Walk 1 Direction	To W		X Walk 2 Dire	ction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Widt	th (in)	N/A
	X Walk 1 Slope (%)	1.3		X Walk 2 Slop	e (%)	N/A
	X Walk 1 X Slope (%)	3.2		X Walk 2 X Sl	ope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside >	(Walk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?		N/A
	Road X Slope (%)	N/A	N/A	Clear Space to	o XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/U	Itility Hazard?	N/A
	Obstruction Type			Storm Grate/U	Jtility Type	
		N/A				N/A

Yes

Surface Condition? (G/P)

Good





