

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8193	Main Street: E_W_T_HARRIS_BV	Cross Street: GRIER_RD	Location: SE
ADA ID: 65338B82E615	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 7.5			



Possible Solutions:

**Remove & Replace Entire Ramp.
Remove & Replace Gutter.**

Surveyor Notes:

N/A

PROW/ADA:

**Not Found, R304.2.2-Perp, R304.3.2-
Para, R304.5.3, R305.2, R302.7,
R302.7.2**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	90.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	67.0	No	Grade Break Slope (%)	5.8
Yes	Ramp Slope (%)	3.2	Yes	Grade Break XSlope (%)	1.1
Yes	Ramp XSlope (%)	1.3			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	60.5	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	72.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	6.0	Yes	DWS Length (in)	25.0
Yes	Landing X Slope (%)	0.5	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	2.0
N/A	Shared Landing?	No	No	DWS Offset RT (in)	67.0
No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	0.3
No	Gutter Lip Ht (in)	0.5	No	Gutter X Slope (%)	5.1
N/A	Painted X Walk1?	Yes		Road Slope (%)	1.8
	X Walk 1 Direction	To W		Road X Slope (%)	2.3
	X Walk 1 Width (in)	141.5		Clear Space?	Yes
	X Walk 1 Slope (%)	1.8	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	2.3	Yes	Storm Grate/Utility Hazard?	No
Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	13.2

Total Cost: \$ 2350.00

