


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A	Main Street: ARDREY_KELL_RD	Cross Street: WAVERLY_WALK_AV	Location: NE
ADA ID: 6569770AB965	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	
	<b>Remove &amp; Replace Entire Ramp.</b>		N/A	Ramp Length (in)	96.0	N/A
			Yes	Ramp Width (in)	96.0	N/A
			No	Ramp Slope (%)	8.8	N/A
			No	Ramp XSlope (%)	2.2	N/A
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Flare Type RT	N/A	N/A
			N/A	Flare Slope RT (%)	N/A	N/A
<p>Surveyor Notes:</p> <p><b>N/A</b></p>			N/A	Flare Traversable RT?	N/A	N/A
			N/A	Landing Length (in)	0.0	N/A
			N/A	Landing Width (in)	0.0	N/A
			N/A	Landing Slope (%)	0.0	N/A
			N/A	Landing X Slope (%)	0.0	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	N/A
			N/A	Gutter Ponding?	0.0	N/A
			N/A	Gutter Lip Ht (in)	0.0	N/A
			N/A	Painted X Walk1?	Yes	N/A
<p>PROW/ADA:</p> <p><b>R304.2.2, R304.5.3</b></p>			To W	Road Slope (%)	1.7	N/A
			105.0	Road X Slope (%)	1.5	N/A
			1.7	Clear Space?	N/A	N/A
			1.5	Clear Space to XWalk (in)	N/A	N/A
			N/A	Storm Grate/Utility Hazard?	N/A	N/A
			Yes	Storm Grate/Utility Type		N/A
			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		N/A
			Yes	Surface Condition? (G/P)	Good	Good
			N/A	Curb Slope (%)	3.0	3.0
<p>Total Cost: \$ 1600.00</p>						

