

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10037315 Main Street: SARDIS_RD Cross Street: N/A Location: SE

ADA ID: 6638596965DA Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name ENTRANCE
Stop Condition-Street 2 StopSign
Street 2 Name SARDIS RE
Stop Condition-Street 1 None

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes: **N/A**

Possible Solutions:

PROW/ADA:

Not Found, R304.2.2, R304.5.3

NCE	
Sign	
RD	
lone	
	Total Cost:

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	58.5	No	Ram	Slope (%)	10.1
Yes	Ramp Width (in)	49.0	No	Ram	XSlope (%)	4.2
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	To W
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	7.4		X Wa	lk 2 Slope (%)	0.0
	X Walk 1 X Slope (%)	1.7		X Wa	lk 2 X Slope (%)	4.3
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	1.9	N/A	Clear	Space?	N/A
	Road X Slope (%)	1.0	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storn	n Grate/Utility Type	
		N/A				N/A

Yes

Surface Condition? (G/P)

Good







3200.00