


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8599	Main Street: HATERAS_AV	Cross Street: IRMA_ST	Location: NW
ADA ID: 6649AA5A3A51	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:	Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	7.4
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.2</p>		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.9
		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	8.6	Yes	Flare Slope RT (%)	6.5
		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
		No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
		No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
		No	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.0
		No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
		N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	5.0
		N/A	Shared Landing?	N/A			
		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.4
		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.7
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To S		X Walk 2 Direction	To E
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	2.8
			X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	2.1
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	2.0	N/A	Clear Space?	Yes
			Road X Slope (%)	4.5	N/A	Clear Space to XWalk (in)	N/A
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
			Obstruction Type			Storm Grate/Utility Type	
					N/A		N/A
					Yes	Surface Condition? (G/P)	Good

Total Cost: \$ 3200.00

