

Access Compliance Report Public Rights-of-Way (Curb Ramps)



8.5 0.2 N/A N/A N/A N/A N/A N/A

> N/A N/A N/A N/A

> N/A

N/A

N/A

N/A N/A

N/A

N/A

Good

Intersection ID: 16485 Main Street: PARK_RD Cross Street: PRINCETON_AV Location: NE

ADA ID: 665E50EC2467 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Surface Condition? (G/P)



Street 1 Name PRINCETON AV
Stop Condition-Street 2 Signal
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solution			Field Measurements/Component Compliance				
Possible Solutions:			Compliance Description		Data	Data Compliance Description	
Remove & Replace En	itire Ram	ıp.	N/A	Ramp Length (in)	65.0	No	Ramp Slope (%)
•			No	Ramp Width (in)	36.0	Yes	Ramp XSlope (%)
			N/A	Flare Type LT	N/A	N/A	Flare Type RT
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?
Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?
N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)
		N/A	Shared Landing?	N/A			
PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)
Not Found, R304.5.1, R304.2.2			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?
				X Walk 1 Direction	To S		X Walk 2 Direction
			N/A	X Walk 1 Width (in)	105.0	N/A	X Walk 2 Width (in)
				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)
				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)
		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	
				Road Slope (%)	N/A	N/A	Clear Space?
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?
Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type
					N/A		





