

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45774	Main Street: CARVER_FALLS_RD			eet:	HART_RD	Location: E			
ADA ID: 6672C2065629	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance:				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:						Compliance Description	
A MARINE	ALL A	Remove & Replace Entire Ramp.	N/	/A	Ramp Length (in)	73.0	Yes	Ramp Slope (%)	5.9
VILLE THEY THE	in Minister	······································	No	0	Ramp Width (in)	45.0	No	Ramp XSlope (%)	5.1
	and the second		N/.	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/	/ <b>A</b>	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
The Article	T here		N/	/ <b>A</b>	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		5	N/	/ <b>A</b>	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
B	ALC YE	Surveyor Notes:	N/	/ <b>A</b>	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	Par S	N/A	N/	/ <b>A</b>	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
El Que	and the		N/	/ <b>A</b>	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
ALL STATES			N/	/ <b>A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	S RD		N/	/ <b>A</b>	Shared Landing?	N/A			
1201	Ser 1	PROW/ADA:	N/	/ <b>A</b>	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Ja at	R304.5.1, R304.5.3	N/.	Α	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A CARLEN AND A CAR			N/	/ <b>A</b>	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
of the second	100				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
			N/	/ <b>A</b>	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CARVER	FALLS RD	-			X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/	/ <b>A</b>	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/	/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

