

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 17182 | Main Street: W_TYVOLA_RD | | | Street: | CITY_PARK_DR | Location: | NE | | |
|--|--------------------------|-----------------------------|---------|--|-----------------------|-----------|-----------------------------|-----------------------------|------|
| ADA ID: 669394BF9B59 | Ramp Type: MedianPerp | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 12.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | E P | Possible Solutions: | | Compliance Description Data | | | Compliance Description Data | | |
| States and the second | E. | Remove & Replace Entire Ram |). | N/A | Ramp Length (in) | 72.0 | No | Ramp Slope (%) | 8.7 |
| | the states | | | Yes | Ramp Width (in) | 118.0 | Yes | Ramp XSlope (%) | 0.2 |
| In the states | Elso m M | 2 | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| 70.5 | 1771 | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| A A A A A A A | | 8 | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| E. C. Star | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| K / R / K | 1.24 | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| A Phin | and the | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | 1 | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| E Con | 10/10/ | | | N/A | Shared Landing? | N/A | | | |
| NEL SUL | 131 | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | Not Found, R304.2.2 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| A BALLEN | 1 . C. M | | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| 10 10 | the second | | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| | THE BOOM | | | N/A | X Walk 1 Width (in) | 112.0 | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name CI | ITY PARK DR | _ | | | X Walk 1 Slope (%) | 2.9 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | Signal | | | | X Walk 1 X Slope (%) | 1.6 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 1650.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |