

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Good

Intersection ID: 11780 Main Street: E 20TH ST **Cross Street: PEGRAM ST** Location:

Overall Compliance: No ADA ID: 6703DCD5DA80 Ramp Type: PerpDiag Initial Pass/Fail: Fail Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

None

Field Measurements/Component Compliance



E 20TH ST Street 1 Name Stop Condition-Street 2 StopSign **PEGRAM ST** Street 2 Name Stop Condition-Street 1

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2

Total Cost: 3200.00 Compliance Description <u>Data</u> Compliance Description Data No N/A Ramp Length (in) 44.0 Ramp Slope (%) 11.4 Yes No Ramp Width (in) 41.0 Ramp XSlope (%) 1.2 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Slope (%) N/A Yes N/A Gutter Lip Ht (in) 2.0 N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SW X Walk 2 Direction To SE N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) X Walk 2 Slope (%) 0.1 4.6 X Walk 2 X Slope (%) X Walk 1 X Slope (%) 1.7 1.1 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 1.0 N/A Clear Space? N/A N/A Road X Slope (%) Clear Space to XWalk (in) N/A 0.2 N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A

Yes

Surface Condition? (G/P)





